



Engineer(s) Name		Items to be ordered	
Client Name and Site Address		No	Description
Safety Issues Identified			Qty
Client Approval to undertake the works inc Safety Issues			
Date	Print		Sign

Asset No	Minor	Major	Item	Service Code	Completed	Comments
009-010		✓	Grundfos Heating Pump LPHW Primary	H034		
073-077		✓	Evaporators Toshiba VRF (East) System D	A047		
078		✓	Air Cooled Toshiba Condenser System D	A018		
079-080		✓	Evaporators Toshiba VRF (West) System E	A047		
081		✓	Air Cooled Toshiba Condenser System E	A018		
082		✓	Evaporator Toshiba MR 02 System S1	A047		
083		✓	Air Cooled Toshiba Condenser System S1	A018		
084		✓	Evaporator Toshiba Lift Lobby Sys/m S2	A047		
085		✓	Air Cooled Toshiba Condenser System S2	A018		
086		✓	Evaporator Toshiba Patch Rm 2 Sys'm S3	A047		
087		✓	Air Colled Toshiba Condenser System S3	A018		
088-089	✓		AHUs Supply East & West	A023		
133-152	✓		Colman VAV Units Second Floor	A017		
163	✓		Water Temperature Checks	L82001		
165	✓		External Lighting	A023		
170		✓	Emergency Lighting	A017		

Client acceptance of Satisfactory Completion of the works		Arrival Time	
Date	Print	Sign	Departure Time

